

IE-352
Section 1, CRN: 13536
Section 2, CRN: 30521
First Semester 1432-33 H (Fall-2011) – 4(4,1,1)
MANUFACTURING PROCESSES - 2

Machining Exercises **Answers**

Name:	Student Number: 42
-------	-----------------------

Answer ALL of the following questions [2 Points Each].

1. Let $n = 0.5$ and $C = 90$ in the *Taylor* equation for tool wear. What is the percent increase in tool life if the cutting speed is reduced by (a) 50% and (b) 75%?

Solution:

Taylor Equation for tool life:

$$VT^n = C$$

$$n = 0.5; C = 90$$

$$\Rightarrow VT^{0.5} = 90 \Rightarrow V_1T_1^{0.5} = V_2T_2^{0.5}$$

a) $V_2 = 0.5V_1$

$$\Rightarrow V_1T_1^{0.5} = 0.5V_1T_2^{0.5}$$

$$\Rightarrow T_1^{0.5} = 0.5T_2^{0.5}$$

$$\Rightarrow \left(\frac{T_2}{T_1}\right)^{0.5} = 2$$

$$\Rightarrow \sqrt{\frac{T_2}{T_1}} = 2$$

$$\Rightarrow \frac{T_2}{T_1} = 4$$

$$\Rightarrow \text{increase in tool life} = \frac{T_2 - T_1}{T_1} = \frac{T_2}{T_1} - 1 = 3$$

\Rightarrow i.e. increase in tool life is 300%

b) $V_2 = 0.25V_1$ (since speed decreases by 75%)

$$\Rightarrow T_1^{0.5} = 0.25T_2^{0.5}$$

$$\Rightarrow \left(\frac{T_2}{T_1}\right)^{0.5} = 4$$

$$\Rightarrow \frac{T_2}{T_1} = 16$$

$$\Rightarrow \text{increase in tool life} = \frac{T_2 - T_1}{T_1} = 16 - 1 = 15$$

\Rightarrow i.e. increase in tool life is 1500% (i. e. 15 – fold)

2. Taking carbide as an example and using the equation for mean temperature in turning on a lathe, determine how much the feed should be reduced in order to keep the mean temperature constant when the cutting speed is doubled.

Solution:

equation for mean temperature in turning on a lathe,

$$T_{\text{mean}} \propto V^a f^b$$

Given: $T_{\text{mean}} = C_1; V_2 = 2V_1; \text{for carbide: } a = 0.2, b = 0.125$

$$\Rightarrow C_1 = C_2 V^{0.2} f^{0.125}$$

$$\Rightarrow V_1^{0.2} f_1^{0.125} = (2V_1)^{0.2} f_2^{0.125}$$

$$\Rightarrow \left(\frac{f_2}{f_1}\right)^{0.125} = 0.5^{0.2}$$

$$\Rightarrow \frac{f_2}{f_1} = 2^{-\left(\frac{0.2}{0.125}\right)} = 2^{-1.6} = 0.330$$

$$\Rightarrow \text{reduction in feed} = \frac{f_1 - f_2}{f_1} = 1 - 0.330 = 0.670$$

\Rightarrow i.e. reduction in feed is 67%

3. An orthogonal cutting operation is being carried out under the following conditions: $t_o = 0.1 \text{ mm}$, $t_c = 0.2 \text{ mm}$, width of cut = 5 mm , $V = 2 \text{ m/s}$, rake angle = 10° , $F_c = 500 \text{ N}$, and $F_t = 200 \text{ N}$. Calculate the percentage of the total energy that is dissipated in the shear plane.

Note, for detailed solution, see similar exercise: "cutting force exercise 2.PDF"

Givens: thicknesses: $t_o = 0.1 \text{ mm}$; $t_c = 0.2 \text{ mm}$

angles: $\alpha = 10^\circ$

velocities: $V = 2 \text{ m/s}$

forces: $F_c = 500 \text{ N}$; $F_t = 200 \text{ N}$; $F_s = ?$; $F_n = ?$

Required: %ge of total energy dissipated in primary shearing zone

$$\text{i.e. } \frac{U_s}{U_{tot}} (100) = \frac{\text{Power}_s}{\text{Power}_{tot}} (100) = ?$$

Solution:

$$\frac{\text{Power}_s}{\text{Power}_{tot}} = \frac{F_s V_s}{F_c V}$$

Strategy: we have F_c and V , and we need to find F_s and V_s

- V_s can be obtained if we have shear angle (ϕ), from,*

$$V_s = V \frac{\cos \alpha}{\cos(\phi - \alpha)}$$

- and ϕ can be obtained from,*

$$\tan \phi = \frac{r \cos \alpha}{1 - r \sin \alpha}$$

- and r can be obtained from,*

$$r = \frac{t_o}{t_c} = \frac{0.1 \text{ mm}}{0.2 \text{ mm}} = 0.5$$

- now, working back \Rightarrow*

$$\phi = \tan^{-1} \left[\frac{0.5 \cos 10^\circ}{1 - 0.5 \sin 10^\circ} \right] = \tan^{-1} 0.539 = 28.3^\circ, \text{ and:}$$

$$V_s = 2 \text{ m/s} \frac{\cos 10^\circ}{\cos(28.3^\circ - 10^\circ)} = (2 \text{ m/s}) * 1.037 = 2.075 \text{ m/s}$$

Note how shear velocity is higher (4%) than cutting speed


- F_s is now required and can be obtained force circle,

by resolving component of

F_c along F_s direction, and

F_t opposite to F_s direction

⇒



$$F_s = F_c \cos \phi - F_t \sin \phi$$

$$= (500 \text{ N}) \cos 28.3^\circ - (200 \text{ N}) \sin 28.3^\circ$$

$$= 440 \text{ N} - 94.9 \text{ N} = 345 \text{ N}$$

- Substituting values of V_s and F_s into $\frac{Power_s}{Power_{tot}} = \frac{F_s V_s}{F_c V} \Rightarrow$

$$\frac{Power_s}{Power_{tot}} = \frac{(345 \text{ N})(2.075 \text{ m/s})}{(500 \text{ N})(2 \text{ m/s})} = \frac{718.875}{1000} = 0.719$$

⇒ %ge of total energy dissipated in shearing is approximately 72%

Note, you can check your answer by calculating %ge of energy dissipated due to friction (which should 28%; see “cutting force exercise 1.PDF”), and adding the two values, which should amount to exactly 100%.

4. For a turning operation using a ceramic cutting tool, if the speed is increased by 50%, by what factor must the feed rate be modified to obtain a constant tool life? Use $n = 0.5$ and $y = 0.6$.

Given:

$$V_2 = V_1 + 0.5V_1 = 1.5V_1$$

$$T_2 = T_1$$

$$n = 0.5; y = 0.6$$

Required: $\frac{f_2}{f_1} = ?$

Solution:

Taylor tool life equation for turning operation:

$$VT^n d^x f^y = C_1 \Rightarrow$$

$$V_1 T_1^n d_1^x f_1^y = V_2 T_2^n d_2^x f_2^y$$

since $T_2 = T_1$, and assuming constant depth of cut (d) \Rightarrow

$$V_1 f_1^y = 1.5V_1 f_2^y \Rightarrow$$

$$\left(\frac{f_2}{f_1}\right)^{0.6} = \frac{1}{1.5} \Rightarrow$$

$$\frac{f_2}{f_1} = 1.5^{-\frac{1}{0.6}} = 0.509$$

\Rightarrow feed must be modified by a factor of 50.9%

5. Using the equation for surface roughness to select an appropriate feed for $R = 1 \text{ mm}$ and a desired roughness of $1 \mu\text{m}$. How would you adjust this feed to allow for nose wear of the tool during extended cuts? Explain your reasoning.

Given:

$$R = 1 \text{ mm} = 1 * 10^{-3} \text{ m}$$

$$R_t = 1 \mu\text{m} = 1 * 10^{-6} \text{ m}$$

Required:

- $f = ?$
- how to adjust feed to account for nose wear

Solution:

- *equation for surface roughness,*

$$R_t = \frac{f^2}{8R} \Rightarrow$$

$$f = \sqrt{(8R)R_t} = \sqrt{(8 * 10^{-3} \text{ m})(1 * 10^{-6} \text{ m})} = \sqrt{8 * 10^{-9} \text{ m}^2} = \\ = 8.94 * 10^{-5} \text{ m/rev} = 0.089 * 10^{-3} \text{ m/rev} \Rightarrow$$

\Rightarrow appropriate feed is 0.089 mm/rev

- *when nose wear occurs \Rightarrow
radius (R) will increase \Rightarrow
to keep the surface roughness (R_t) the same*

\Rightarrow the feed must also increase