



Lab-01 Chapter-01

YOUR FIRST PART – START TO FINISH

2



THREE DIMENSIONAL PART GENERATION IS VERY EASY AND FOLLOWS A LOGICAL PROGRESSION WHEN YOU KNOW HOW TO USE A FEW ICONS...

going from THIS... to THIS... to THIS...

Catia is "WINDOWS" based and ICON driven...Something most of us are already used to.

Is as easy as 1...2...3!

5

This is the first screen you will encounter on the way to making your part. There are a few primary choices you will make here that determine the outcome of your part...

Part tree: xy plane, yz plane, zx plane, PartBody

Then, pick **SKETCHER** from the toolbar on the right.

Firstly, choose which plane that you wish to sketch in.

To keep it simple, pick the "xy plane" when beginning a part. This will help you to draw in a familiar plane.

The **PART TREE** always tells you where you are. Notice at the top it says PART1 and at the bottom it is waiting for you to do something with **PartBody**.

6

Now you are in **SKETCHER**. From here you pick an icon from the **PROFILE** toolbar and *Click-and-Draw* that shape in the sketcher environment.

Notice the Part Tree reflects the fact that you are working on Sketch1.

This is the **PROFILE** toolbar. These shapes are easy to use and the icons are self explanatory.

This square was drawn using the square icon in the sketcher environment.

At this point you are just roughing in the shape. The exact dimensions will be added next if needed.

7

To **CONSTRAIN**, or dimension a part, first click on the line to be done as shown here...

Click the line and click on Normal Constraint for the dimension to appear...double click to change the dimension that appears...

This is the **CONSTRAINTS** toolbar...

Defined in dialog box...
Normal constraint...
Auto Constraint...
Animate constraint...
Exit Sketcher...


Constraints are used throughout Catia and can be demanding. A later chapter will be devoted just to them.

Once you have all of the required parts dimensioned, you are ready to go into 3D mode...

Click **EXIT** for Catia to leave the sketcher mode and enter 3D modeller...

8


Once you enter the 3D environment, the part profile you were working on takes on an isometric orientation as seen here.




Notice that not all of the icons shown on the shortened SKETCHER toolbar are active. This is because some other variable must be satisfied for Catia to allow it's use. We will cover all of the icons and their uses later.

Once PAD is chosen, the PAD DEFINITION pop-up will appear. From here you define the TYPE and LENGTH of the pad. You can also choose to mirror the pad or reverse it's direction from here.

This is the SKETCHER toolbar from which you can choose a process of building your 3D model...here we have chosen PAD





Pad icon




9

The pad definition box will cause the limits that have been selected to be applied in a wire frame representation first. Now if you click on APPLY and then OK, your wire frame will finally become a solid 3D model.

Notice that on your PARTS TREE, pad1 has been added BEFORE sketch1 that was already there. This is all part of Catia's hierarchy system.





Congratulations! Your FIRST 3D part!





10




Lab-02 Chapter -02

BASIC DRESS-UP FEATURES

11








Lab-03 **Chapter-03**

MOUSE MANIPULATION

23


The 3 button mouse is your tool for manipulation of the parts and assemblies that you have created. With it you can ZOOM, ROTATE and PAN your parts or manipulate the specification tree. First, place your cursor ANYWHERE on the screen...



To ZOOM, click and hold the MIDDLE mouse button, click and release the LEFT mouse button, then PUSH the mouse away from you to make your part smaller and PULL it towards you to enlarge your part.

24

ZOOM in from a small part...




To a LARGE part with this simple technique.

25





The next thing you can do is ROTATE your part...

CLICK AND HOLD FIRST
CLICK AND HOLD SECOND



This is accomplished by HOLDING the MIDDLE mouse button and then the LEFT mouse button while keeping the middle one depressed.

26



The tree responds the same as a part does for manipulation. To move the tree, simply place the cursor near it and click and hold the middle mouse button. Now drag the tree wherever you wanted it.

FROM HERE...

TO HERE...

Here we have moved the tree by dragging it from one corner of the screen to the other.

31

By using the same mouse clicks to ZOOM as you did with a part, you can make your tree larger or smaller as you need to.

TO THIS...

FROM THIS...

Click and hold the middle mouse button, while single clicking the left mouse button. While holding the middle button, move the mouse toward and away from you to make the tree bigger or smaller

32

To SHRINK or EXPAND your specification tree, you simply click on the + or – signs.

CLICK HERE TO OPEN TO THIS...

Clicking a + opens up the tree into it's individual branches. Clicking a – does the reverse.





33

Different RENDERING STYLES give you different views of your part. The most common one is SHADING. It is chosen by clicking on it in the VISUALIZATION toolbar.

VISUALIZATION TOOLBAR

SHADING




34











Lab-03 Chapter-04


ADVANCED DRESS-UP FEATURES

39










Lab-04


Chapter Five

CONSTRAINTS


52







53







54



55







Lab-05 Chapter-06

REFERENCE ELEMENTS


64







65









66



67









Lab-05 Chapter-07

BASIC ASSEMBLY DESIGN





79









81






82










Lab-06 Chapter-08

DRAFTING and DIMENSIONING


98



99




100




101

The NEW DRAWING CREATION dialog box will appear.
The first thing to do is pick your automatic layout.




Next, you can choose MODIFY and change ISO and ANSI standards, number of sheets and orientation, scale and others.

102




103









104

If default is **DIAMETER**, this is what you will see. If you wish to dimension a **RADIUS**, highlight the line and **right click** on it.




105







Click on **GENERATING DIMENSIONS Step By Step**. This will allow CATIA to do the dimensioning for you one at a time, every few seconds, whatever timeout you choose.



Once all of the automatic dimensioning is finished, you will get an **ANALYSIS** of what was done.






Lab-07 Chapter- 09


DRAWING USING SURFACES

115



Now we will profile an auto body...

The first thing you will want to do is layout your guide lines. You can do this by choosing **POINT** from the toolbar, and putting them where you need them.




The first one you place is at the origin, or 0,0,0.
Hit OK.




Then place one at x=50 and one at x= -50 so that you are working off of a reference point.

117

Choose **LINE** from the toolbar, and the Line Definition dialog box will appear.




In **LINE TYPE**, pick Point-Point, then choose the x=50 point as point 1 and x=-50 as point 2. Hit OK.



Now we can copy the newly created line over 25mm. To do this click **TRANSLATE** from the toolbar, choose the line as **ELEMENT**, ZX plane as the direction and 25mm as the distance.

118

We can now **RENAME** the first line we made as Centreline. To do this, put your pointer on the line to highlight it and right click on it. Then choose **PROPERTIES**.




At the **Properties screen**, choose the Feature Properties tab (click on "**more**" if you get the **short** dialog box) highlight name by clicking on it and type **centreline**.

Hit OK to return to the work view. Now we can start to make the auto body shape.

119

Choose the ZX plane and then click on **SKETCHER**. It is here that we are going to put in the points to define the basic car shape as shown.


Pick **point** and lay out the points roughly as shown. (If you **double click point**, it will stay active to do more than one point at a time).




Now choose **SPLINE** and join all of the points to form one smoothly curved line. This is now your basic car shape.

120

Now we can do a few **TRANSLATIONS** at the same time. First, click the **TRANSLATE** icon, then Sketch1 is the element, ZX plane is the Direction and distance is 25mm.




Choose Translate again. This time Translat.1 from the specification tree is the element, ZX plane is again the direction, and the distance is -85mm. Rename this line centrelines2.




121

We now need to add some lines to the front and back of the car to guide the surfaces there. Join the centreline and translat.1 with a line. Rename it **SIDE SURFACE GUIDE**.




Now **TRANSLATE** that line 20mm in using Side Surface Guide as the element, Translat.1 As the direction. Rename it Side Surface Centre.

Join the other end of the car with a line, but do not translate it, as we will use Side Surface Centre as the centre of the curved surface.



122


Now make the first surface using **EXTRUDE**. Click on the icon, in the dialog box pick Translat.2 as Profile. ZX Plane as Direction and extrusion Limit 1 as 25mm. Reverse direction if needed, and click OK. Rename it TOP.



123




Now click the SWEEP icon. Choose CIRCLE as the Profile type.



With the Guide Curve tab picked, choose Translat.1 as the Guide Curve 1.


124

Now pick the Center Curve tab. Centreline2 is the Center curve, Translat1 is the Reference angle curve. Enter -20 in the angle 2 area. Now click OK.




125





Now we can do the front and back surfaces...



Choose **SWEEP** again and enter the information as done here using the previously renamed lines...



126



Lab: CAD/CAM

Title: NC Manufacturing With Catia V5

Introduction

NC Manufacturing Infrastructure in a Nutshell

NC Manufacturing Infrastructure offers the following main functions:

- Common platform for 2.5 to 5-axis axis machining capabilities, which include mill, drill and turn operations
- Management of tools and tool catalogs
- Flexible management of the manufacturing program with intuitive and easy-to-learn user interface based on graphic dialog boxes
- Tight interaction between tool path definition, verification and generation
- Knowledge ware customization facilities through f(x) formula and Edit search facilities
- Seamless NC data generation thanks to an integrated Post Processor Access solution
- Automatic shop floor documentation in HTML format


Set Up and Part Positioning


You must create a CAT Product entity for each part set up you want to represent.

1. Enter a Machining workbench and double-click the Part Operation.1 entity in the tree.






The Part Operation dialog box appears.


2. Click **Product or Part**  to associate a product to the part operation.



3. Select a CATProduct from the Associated Product list, then click **Open** to display the corresponding part set up.




4. Click OK in the Part Operation dialog box.
5. Click **Part Operation**  to create the Part Operation.2 entity in the tree.
6. Associate another product to Part Operation.2 in the same way as described above.
7. Click OK in the Part Operation dialog box.



To display the desired part set up, just select the corresponding Part Operation in the tree

Manage Workbenches

- 1 Select File > Open then select the desired CATPart document.
- 2 Select Machining > Prismatic Machining from the Start menu. The Prismatic Machining workbench appears. The part is displayed in the Setup Editor window along with the PPR specification tree.



The CATPart is automatically associated to the Part Operation and an instance of the part is created in the Product List.

- 3 Select Manufacturing Program.1 in the tree to make it the current entity.
To insert program entities such as machining operations, tools and auxiliary commands you can either:
 - make the program current before clicking the *insert program entity* command
 - click the *insert program entity* command then make the program current.
- 4 Double-click the Part entity in the tree to switch to a Mechanical Design workbench (such as Part Design or Wireframe and Surface Design depending on your configuration).
- 5 Double-click a Machining entity in the tree to switch back to the Machining workbench

Prismatic Machining in a Nutshell

Prismatic Machining enables you to define and manage NC programs dedicated to machining parts designed in 3D wireframe or solids geometry using 2.5 axis machining techniques.

It offers an easy-to-use and easy-to-learn graphic interface that makes it suitable for shop floor-oriented use. Moreover, its leading edge technologies together with a tight integration with Version 5 design methodologies and DELMIA's digital manufacturing environment, fully satisfy the requirements of office programming. Prismatic Machining is a unique solution that reconciliates office and shop floor activities.



It is integrated to a Post Processor Access execution engine, allowing the product to cover the whole manufacturing process from tool trajectory (APT source) to NC code.

This product is particularly adapted for tooling and simple machined parts, and is also an ideal complement to other manufacturing applications.

Prismatic Machining offers the following main functions:


- 2.5 axis milling and drilling capabilities
- Management of tools and tool catalogs
- Flexible management of the manufacturing program with intuitive and easy-to-learn user interface based on graphic dialog boxes
- Tight interaction between tool path definition, verification and generation
- Seamless NC data generation thanks to an integrated Post Processor Access solution
- Automatic shop floor documentation in HTML format

Step 01: Enter the Workbench

-  This first task shows you how to open a part and enter the Prismatic Machining workbench.
-  1. Select **File > Open** then select the [GettingStartedPrismaticMachining.CATPart](#) document.
2. Select **Machining > Prismatic Machining** from the Start menu.


The Prismatic Machining workbench appears.

The part is displayed in the Setup Editor window along with the manufacturing specification tree.



3. Select **Manufacturing Program.1** in the tree to make it the current entity.
- To insert program entities such as machining operations, tools and auxiliary commands you can either:
- Make the program current before clicking the *insert program entity* command
 - Click the *insert program entity* command then make the program current.


Step: 02 Create a Pocketing Operation


 This task shows you how to insert a pocketing operation in the program.

As this operation will use the default tool and options proposed by the program, you just need to specify the geometry to be machined.

-  1. Select **Pocketing**  in the Machining Operations toolbar.

A Pocketing.1 entity along with a default tool is added to the program.




The Pocketing dialog box appears directly at the **Geometry** tab page .

The red status light on the tab indicates that you must select the pocket geometry in order to create the operation.

The Geometry page includes an icon representing a simple pocket.

There are several sensitive areas and texts in the icon to help you specify the pocket geometry. Sensitive areas that are colored red indicate required geometry.

Make sure that the Pocketing style is set to **Closed Pocket**. Click on the **Open Pocket** text if this is not the case.



2. Right-click the red Bottom in the icon and select **Contour Detection**.

Click the red Bottom area.


The dialog box is reduced allowing you to select the corresponding part geometry.

3. Select the bottom of the pocket.

The boundary of the selected pocket bottom is automatically proposed as guiding element for the operation thanks to the Contour Detection setting


The dialog box reappears.

The bottom and sides of the pocket in the icon are now colored green, indicating that the corresponding geometry is defined for the operation. The tab status is now green .



4. Click **OK** to create the operation.


Step: 03 Replay the Tool Path

 This task shows you how to replay the tool path of the pocketing operation.

-  1. Select the pocketing operation in the tree then select **Replay Tool Path** .


The tool path is computed and the Replay dialog box appears.

2. Choose a **Point by Point** replay of the tool path.





You can set the number of computed points to be replayed at each step of the verification by means of the spinner.




3. Click rewind button to position the tool at the start point of the operation.
4. Click the play button to start the replay and continue to click that button to move the tool along the computed trajectory.
5. Click **OK** to quit the replay mode.



Step: 04 Create a Profile Contouring Operation

 This task shows you how to insert a profile contouring operation in the program.

 Make sure that the pocketing operation is the current entity in the program.

-  1. Select **Profile Contouring** .
The Profile Contouring dialog box appears directly at the **Geometry** page .

Make sure the Contouring mode is set to **Between Two Planes**.


2. Click the **Bottom:**
Hard text in the sensitive icon to switch the type of bottom to Soft.
3. Click the Bottom plane then select the corresponding part geometry (that is, the underside of the part).


The closed external contour of the bottom is proposed as Guide element for the operation.

 Make sure that the arrow on the Guide element is pointing away from the part.

4. Click the Top plane in the icon, then select the corresponding part geometry.
5. Double click **Offset on Contour** in the icon.

Set this value to 1mm in the Edit Parameter dialog box and click **OK**.



6. Select the **Strategy** tab page  and set the parameters as shown.

Tool path style: One way

Machining | Stepover | Finishing | HSM

Sequencing: Radial first ?

Radial Strategy (Dr)

Distance between paths: 1mm ? Number of paths: 1 ?

Overhang for rework areas: 50

Axial Strategy (Da)

Mode: Number of levels ?


Maximum depth of cut: 4mm Number of levels: 5

Automatic draft angle: 0deg ?


Breakthrough: 0mm ?

7. If needed, you can change the tool axis orientation. Just click the Tool Axis symbol then click the **Reverse Direction** button in the Tool Axis dialog box.

You can display the tool with the specified orientation by selecting the Display tool checkbox.




8. Click **Preview** in the dialog box to request that the program verifies the compatibility of the selected tool, geometry and machining parameters. A message box appears giving feedback about this verification.
9. Click **Replay** in the dialog box to visually check the operation's tool path.



At the end of the replay click **OK** to return to the Profile Contouring dialog box.


10. Click **OK** to create the operation.

Step:5 Create a Drilling Operation


 This task shows you how to insert a drilling operation in the program.

1. Select **Drilling** .

The Drilling dialog box appears directly at the **Geometry** page .

 The program is updated to include a Drilling operation.

The Drilling dialog box appears.




2. Select the red hole depth representation in the sensitive icon.

The Pattern Selection dialog box appears to help you specify the pattern of holes to be machined.


3. Select the cylindrical feature of the first hole.
4. Select the second hole feature, then double click to end hole selection.

The Drilling dialog box replaces the Pattern Selection dialog box.

The icon is updated with geometric information about the first selected hole of the pattern.







5. Double click **Jump distance** in the sensitive icon, then enter a value of 5mm in the Edit Parameter dialog box.
6. Click **Preview** in the dialog box to request that the program verifies the compatibility of the selected tool, geometry and machining parameters. A message box appears giving feedback about this verification.
7. Click **Replay** to replay the operation as described previously.




Click **OK** to return to the Drilling dialog box.


8. Click **OK** to create the Drilling operation in the program.

Step:6 Assign a Tool

-  This task shows you how to assign another tool to an operation.
-  1. Double-click the Profile Contouring operation in the program, then in the **Tooling** tab page , select the **Tool** tab .
2. Enter a name of the new tool (for example, 16mm Flat Milling Tool).



3. Double-click **D** (nominal diameter) in the sensitive icon, then enter 16mm in the Edit Parameter dialog box. The tool icon is updated to take the new value into account.
4. Double-click **Rc** (corner radius) in the icon, then enter 0mm in the Edit Parameter dialog box.
- Set **db** (body diameter) to 24mm in the same way.
- The Tool number is set to 2.



5. Click **OK** to accept the new tool.
The program is automatically updated.

You can modify the tools of the other operations in the same way. For example, you may want to replace the End Mill by a Drill in the Drilling operation.

Step:7 Generate NC Code



This task shows you how to generate NC data in APT format from the program.

For more information about this procedure please refer to [Program Output](#).

1. Right-click the Manufacturing Program.1 entity in the tree and select **Manufacturing Program.1 object > Generate NC Code Interactively**. The Generate NC Output Interactively dialog box appears.

2. Select APT as the desired NC data type.
3. Click **Output File** to select the folder where you want the file to be saved and specify the name of the file.
4. Click **Execute** to generate the APT source file.

An extract from a typical APT source file is given below.

```
$$ -----
$$ Generated on Thursday, May 10, 2001 04:58:20 PM
$$ -----
$$ Manufacturing Program.1
$$ Part Operation.1
$$*CATIA0
$$ Manufacturing Program.1
$$ 1.00000 0.00000 0.00000 0.00000
$$ 0.00000 1.00000 0.00000 0.00000
$$ 0.00000 0.00000 1.00000 0.00000
PARTNO PART TO BE MACHINED
COOLNT/ON
CUTCOM/OFF
PPRINT OPERATION NAME : Tool Change.1
$$ Start generation of : Tool Change.1
TLAXIS/ 0.000000, 0.000000, 1.000000
$$ TOOLCHANGEBEGINNING
RAPID
GOTO / 0.00000, 0.00000, 100.00000
CUTTER/ 10.000000, 2.000000, 3.000000, 2.000000, 0.000000$
, 0.000000, 100.000000
TOOLNO/1, 10.000000
TPRINT/T1 End Mill D 10
LOADTL/1
$$ End of generation of : Tool Change.1
PPRINT OPERATION NAME : Pocketing.1
$$ Start generation of : Pocketing.1
FEDRAT/ 1000.0000,MPPM
SPINDL/ 70.0000,RPM,CLW
GOTO / 30.61644, 2.50000, 5.00000
GOTO / 17.50000, 2.50000, 5.00000
...
GOTO / 30.61644, 35.00000, 5.00000
$$ End of generation of : Pocketing.1
PPRINT OPERATION NAME : Tool Change.2
$$ Start generation of : Tool Change.2
$$ TOOLCHANGEBEGINNING
RAPID
GOTO / 0.00000, 0.00000, 100.00000
CUTTER/ 16.000000, 0.000000, 8.000000, 0.000000, 0.000000$
, 0.000000, 100.000000
TOOLNO/2, 16.000000
TPRINT/16 Flat Milling Tool
LOADTL/2
$$ End of generation of : Tool Change.2
PPRINT OPERATION NAME : Profile Contouring.1
$$ Start generation of : Profile Contouring.1
FEDRAT/ 300.0000,MPPM
SPINDL/ 70.0000,RPM,CLW
GOTO / -69.00000, 40.00000, 46.00000
...
GOTO / -69.00000, 50.00000, 0.00000
$$ End of generation of : Profile Contouring.1
PPRINT OPERATION NAME : Tool Change.3
$$ Start generation of : Tool Change.3
$$ TOOLCHANGEBEGINNING
RAPID
```



```
GOTO / 0.00000, 0.00000, 100.00000
CUTTER/ 9.000000, 0.000000, 4.500000, 2.598076, 30.000000$
, 0.000000, 100.000000
TOOLNO/3, 9.000000
TPRINT/9mm Drill
LOADTL/3
$$ End of generation of : Tool Change.3
PPRINT OPERATION NAME : Drilling.1
$$ Start generation of : Drilling.1
LOADTL/3,1
SPINDL/ 70.0000,RPM,CLW
RAPID
GOTO / -40.00000, -30.00000, 25.00000
RAPID
GOTO / -40.00000, -30.00000, 21.00000
CYCLE/DRILL, 10.000000, 1.000000, 1000.000000,MMPM
GOTO / -40.00000, -30.00000, 20.00000
GOTO / -40.00000, 30.00000, 20.00000
CYCLE/OFF
RAPID
GOTO / -40.00000, 30.00000, 21.00000
RAPID
GOTO / -40.00000, 30.00000, 25.00000
$$ End of generation of : Drilling.1
SPINDL/OFF
REWIND/0
END
```