

IE-352

Section 1, CRN: 48703/4/5

Section 2, CRN: 48706/7/8

First Semester 1436-37 H (Fall-2015) – 4(4,1,2)

“MANUFACTURING PROCESSES – 2”

Thursday, November 26, 2015 (14/02/1437H)


HW 2 (MIDTERM 2)

Name:	Student Number:	Section:
	4	Darwish / Sherb.

Place the correct letter in the box at the right of each question [0.5 Pt. Each]

1. Label the ... cutting tool diagram shown below.

- A. HSS; ① : wear land; ② : crater wear; ④ : oxidation wear
- B. carbide; ① : DOC line; ② : failure face; ④ : outer-metal chip notch
- C. HSS; ① : DOC line; ② : failure face; ④ : outer-metal chip notch
- D. ceramic; ① : wear land; ② : crater wear; ④ : failure face
- E. ceramic; ① : wear land; ② : crater wear; ④ : oxidation wear



2. An increase in shear strain is associated with ...

- A. decrease in shear angle; decrease in rake angle; decrease in friction angle
- B. decrease in shear angle; decrease in rake angle; increase in friction angle
- C. decrease in shear angle; increase in rake angle; increase in friction angle
- D. increase in shear angle; decrease in rake angle; decrease in friction angle
- E. increase in shear angle; increase in rake angle; increase in friction angle

3. ... chips have a ... area of low γ and a ... area of high γ .

- A. segmented; large; small
- B. discontinuous; large; small
- C. segmented; small; large
- D. discontinuous; small; large
- E. BUE; large; small

4. Which of the following should have the highest hardness?...
- A. workpiece
 - B. BUE chip
 - C. tool
 - D. continuous chip
 - E. segmented chip
5. The units of which of the following two properties are the same?
- A. u_t and V
 - B. u_t and mechanical efficiency
 - C. u_t and r
 - D. u_t and specific cutting force
 - E. u_t and material removal rate
6. The product of (*cut material width * depth of cut * cutting speed*) is known as...
- A. power
 - B. specific force
 - C. specific energy
 - D. total energy
 - E. material removal rate
7. Equation for mean temperature in turning on a lathe shows that ...
- A. HSS tools heat up more than carbide tools; V has a greater effect on temp. than f
 - B. HSS tools heat up more than carbide tools; f has a greater effect on temp. than V
 - C. carbide tools heat up more than HSS tools; f has a greater effect on temp. than V
 - D. carbide tools heat up more than HSS tools; V has a greater effect on temp. than f
 - E. HSS tools heat up more than carbide tools; f and V have the same effect on temp.
8. According to the Taylor Equation, tool life in turning decreases most with ...
- A. increase in feed
 - B. increase in rake angle
 - C. increase in friction
 - D. increase in cutting speed
 - E. increase in cutting depth

9. **Feed marks generated due to turning become *less visible* as a result of ...**
- A. higher feed; duller tool
 - B. lower feed; duller tool
 - C. higher feed; sharper tool
 - D. lower feed; sharper tool
 - E. higher feed; higher speed
10. **Vibration causes ... while chatter causes ...**
- A. chipping and premature failure in diamond tools; changes in cutting dimensions
 - B. changes in cutting dimensions; chipping and premature failure in HSS tools
 - C. changes in cutting dimensions; chipping and premature failure in carbide tools
 - D. changes in cutting dimensions; chipping and premature failure in diamond tools
 - E. chipping and premature failure in HSS tools; changes in cutting dimensions
11. **Removing a large amount of material at high speeds is termed...**
- A. shaving
 - B. finish machining
 - C. rough machining
 - D. skiving
 - E. end milling
12. ***S* and *P* are added to increase the machinability of which steel type?**
- A. free-machining steels
 - B. stainless steels
 - C. carbon steels
 - D. alloy steels
 - E. calcium-deoxidized steels
13. **Which of the following workpiece materials have a tendency to form a BUE?**
- A. gray irons and aluminum
 - B. martensitic steels and copper
 - C. ferritic steels and cobalt-based alloys
 - D. leaded steels and beryllium
 - E. magnesium and zirconium

14. Which workpiece materials listed below pose an environmental toxicity hazard?

- A. gray irons and tungsten
- B. ferritic steels and cobalt-based alloys
- C. martensitic steels and copper
- D. magnesium and zirconium
- E. leaded steels and beryllium

Questions 15-20. In an orthogonal cutting operation using a HSS tool ($n = 0.1$), $t_o = 0.17 \text{ mm}$, $\alpha = 24^\circ$ and the $w = 6 \text{ mm}$. It is observed that $t_c = 0.27 \text{ mm}$, $F_c = 350 \text{ N}$ and $F_t = 200 \text{ N}$.

15. What is the value of the *chip-thickness ratio*?

- A. 1.59
- B. 0.05
- C. 0.27
- D. 0.63
- E. 0.17

16. What is the value of the *shear angle*?

- A. 31.1°
- B. 37.7°
- C. 58.9°
- D. 45.0°
- E. 52.3°

17. What is the value of the *resultant force*?

- A. 550 N
- B. 265 N
- C. 403 N
- D. 350 N
- E. 200 N

18. What is the value of the *friction angle and coefficient of friction*?

- A. 36.3° ; 0.74
- B. 29.7° ; 0.57
- C. 53.7° ; 0.57
- D. 29.7° ; 1.36
- E. 53.7° ; 1.36

19. Find the percentage of total power that goes into overcoming friction?

- A. 58.5%
- B. 41.5%
- C. 92.9%
- D. 67.8%
- E. 32.2%

20. What is the effect on *tool life* of increasing the cutting speed by 50%?

- A. reduction in tool life by 1.7%
- B. reduction in tool life by 57.7%
- C. reduction in tool life by 98.3%
- D. reduction in tool life by 42.3%
- E. reduction in tool life by 66.7%

Rules:

- You must prepare and submit the homework **individually**.
- Your work must be **neatly written** in pencil (or typed) and in **proper English** (where applicable).
- **You must show all work.**
- **BOX** your answer(s) and include the **units**.

Due date:

- **Sunday, December 06, 2015 (24/02/1437)**

Equations, Data, Diagrams You May Find Useful

$$\log x^p = p \log x, \quad \log xy = \log x + \log y, \quad \log \frac{x}{y} = \log x - \log y$$

$$\tan \phi = \frac{r \cos \alpha}{1 - r \sin \alpha} \Rightarrow r = \frac{t_0}{t_c} = \frac{\sin \phi}{\cos(\phi - \alpha)} \quad \alpha_e = \sin^{-1}(\sin^2 i + \cos^2 i \sin \alpha_n)$$

$$r = \frac{t_0}{t_c} = \frac{V_c}{V}$$

$$\gamma = \frac{AB}{OC} = \frac{AO}{OC} + \frac{OB}{OC} \Rightarrow \gamma = \cot \phi + \tan(\phi - \alpha)$$

Shear Stress =

$$\frac{F_s}{\text{Area of the shear plane}}$$

$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos \alpha} = \frac{V_c}{\sin \phi}$$

$$\phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2} \quad (\text{when } \mu = 0.5 \sim 2)$$

$$\Rightarrow \phi = 45^\circ + \alpha - \beta$$

$$VT^n d^x f^y = C$$

$$T = C^{1/n} V^{-1/n} d^{-x/n} f^{-y/n}$$

$$T \approx C^7 V^{-7} d^{-1} f^{-4}$$

$$T = \frac{0.000665 Y_f}{\rho c} \sqrt[3]{\frac{V t_0}{K}}$$

$$\text{Power} = F_c V$$

$$\text{Power for friction} = F V_c$$

$$\text{Power for shearing} = F_s V_s$$

$$R_t = \frac{f^2}{8R}$$

$$T_{\text{mean}} \propto V^a f^b$$

- Carbide tools: $a = 0.2, b = 0.125$
- High-speed steel tools: $a = 0.5, b = 0.375$

$$u_t = u_s + u_f \quad u_s = \frac{F_s V_s}{w t_0 V}$$

$$u_f = \frac{F V_c}{w t_0 V} = \frac{F r}{w t_0}$$

$$\eta_{\text{mech}} = \frac{\text{Power}_c}{\text{Power}_{\text{source}}}$$


$$\mu = \tan \beta = \frac{F}{N} = \frac{F_t + F_c \tan \alpha}{F_c - F_t \tan \alpha}$$

$$F_s = F_c \cos \phi - F_t \sin \phi$$

$$F_n = F_c \sin \phi + F_t \cos \phi$$


Ranges of n Values for the Taylor Equation (21.20a) for Various Tool Materials

High-speed steels	0.08–0.2
Cast alloys	0.1–0.15
Carbides	0.2–0.5
Coated carbides	0.4–0.6
Ceramics	0.5–0.7




- Recommended cutting speed is one producing tool life:
 - 60-120 min: high-speed steel tools
 - 30-60 min: carbide tools

$$F_t = R \sin(\beta - \alpha) \quad \text{or} \quad F_t = F_c \tan(\beta - \alpha)$$



(a)



(b)

Approximate Range of Energy Requirements in Cutting Operations at the Drive Motor of the Machine Tool (for Dull Tools, Multiply by 1.25)

Material	Specific energy $W \cdot s/mm^3$
Aluminum alloys	0.4–1
Cast irons	1.1–5.4
Copper alloys	1.4–3.2
High-temperature alloys	3.2–8
Magnesium alloys	0.3–0.6
Nickel alloys	4.8–6.7
Refractory alloys	3–9
Stainless steels	2–5
Steels	2–9
Titanium alloys	2–5